ACE Home Inspection Service

Property Inspection Report





12345 Oak, St Clair Shores, MI 48081 Inspection prepared for: Frank Starkey & Sally Starkey Real Estate Agent: Mary Test - Upper Clair Realty

Date of Inspection: 8/15/2012 Time: 11:45am Age of Home: 55 Size: 1400 Weather: sunny warm 85 degrees

Inspector: Randy Nasuti NACHI #13071901 18989 Holbrook, Eastpointe, MI 48021 Phone: 586-764-0199 Fax: 586-778-0239

Email: randy@acehomeinsp.com acehomeinsp.com

| ACE Home Inspection Service | 12345 Oak, St Clair Shores, M |
|--|--------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| Thank you for your business! I will happily answer any questions an new home, FOREVER! | bout this report or about your |

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire closing process. Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFI outlets may not be installed; this report will focus on safety and function, not current code. This report identifies specific noncode, non-cosmetic concerns that the inspector feels may need further investigation or repair. For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

Inspection Details

| 1. Attendance | |
|---------------|---|
| | In Attendance: Client present • Buyer Agent present • owner present |
| 2. Home Type | |
| | Home Type: Detached • Single Family Home • Ranch Style |
| 3. Occupancy | |
| | Occupancy: Occupied - Furnished |


Grounds

1. Driveway and Walkway Condition

| | Good | Fair | Poor | N/A | None |
|---|----------|------|------|-----|------|
| ĺ | | | | | |
| l | / | | | | |

Materials: Concrete driveway noted. • Concrete sidewalk noted. Observations:

• The driveway is improperly sloped towards the foundation. Water can infiltrate into the interior. Recommend repairing (pump jacking)or replacing the drive to properly slope away from the foundation.



drive pitching wrong way toward house - possible water intrusion if left unrepaired

2. Grading

| _ | Good | Fair | P001 | IN/A | None |
|---|------|------|------|------|------|
| | < | | | | |

Observations:


• No major system safety or function concerns noted at time of inspection.

3. Vegetation Observations

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| | | | | |
| / | | | | |

Observations:

• Trim trees that are in contact or proximity to home, as branches can abrade roofing or siding.



trim vegetation at least 1 foot from wall

4. Gate Condition

| Good | Fair | Poor | N/A | None | Materials: Chain link |
|------|------|------|-----|------|--------------------------------------|
| | > | | | | Observations: |
| | | | | • | Gate is sagging. |

5. Patio and Porch Deck

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | l 1 |
| | | | | |

6. Stairs & Handrail

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| < | | | | |
| - | | | | |

Observations:

• Cement patio Appeared functional at time of inspection.



unequal step risers can be a tripping hazard @ front porch/entry

7. Grounds Electrical





Broken GFI cover / exposed wires routed through brick wall



ground wire run through the cement driveway unsleeved



conduit separated- missing sleeve where directed through concrete - back patio- consult licensed electrician

| 0 | \sim | _ | \sim |
|----|--------|---|--------|
| 8. | G | | |
| | | | |

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | |
| | | | | |
| | | | | 1 1 |

Observations:

- Missing cover on outside front porch GFI box
- Conduit seperation at both front porch and rear patio electric feeds. Exposed wires. Recommend further evaluation by a licensed electrician.

9. Main Gas Valve Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| ~ | | | | |

Materials: Main gas shut off located at outside meter - East side.

Observations:

• Meter located at exterior. All gas appliances have cut-off valves in line at each unit. No gas odors detected.

10. Plumbing

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| | | | | |
| / | | | | |

Materials: Copper piping noted. • Galvanized piping noted.

11. Water Pressure

| Good | Fair | Poor | N/A | None | Ob 1: |
|----------|------|------|-----|------|---------------|
| | | | | | Observations: |
| / | | | | | • 50 |

12. Pressure Regulator

| Good | Fair | Poor | N/A | None | Ob |
|------|------|------|-----|------|---------------|
| | | | | | Observations: |
| | | | V | l | None. |

13. Exterior Faucet Condition

| Good | Fair | Poor | N/A | None | Location: East side of house. • South side of house. |
|----------|------|------|-----|------|--|
| | | | | | Location. East side of house. • South side of house. |
| / | | | | | Observations: |

• Appears Functional. Caulk where spigot meets the house wall to prevent moisture intrusion - recommend handyman services



caulk needed at faucet to prevent water intrusion

14. Balcony

| Good Fair | Poor | 11/7 | None |
|-----------|------|----------|------|
| | | | |
| | | / | |
| | | | |

15. Patio Enclosure

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | ~ | |

16. Patio and Porch Condition

| Good | Fair | Poor | N/A | None | Observations |
|------|------|------|-----|------|--|
| | | | | | Observations: |
| ~ | | | | | No major system safety or function concerns noted at time of inspection. |

.____

17. Fence Condition

| Good | Fair | Poor | N/A | None | Materials: chain link |
|------|------|------|-----|------|-------------------------|
| | | | | | Materials. Chairi iirik |
| | | | | | |

18. Sprinklers

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | |
| | | | | I 1 |

Garage

1. Roof Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | / | | | |
| | | | | |

Materials: Roof is beyond its intended service life

Materials: Asphalt shingles noted.

Observations:

- No major system safety or function concerns noted at time of inspection.
- Moss on roof. This can lead to the premature failure of the roof and subsequent leaks. Recommend treating moss during its growing season (wet months) with a moss killer. For information on various moss treatment products and their pros and cons, visit

http://bryophytes.science.oregonstate.edu/page24.htm.

Exposed nails on roofing material. Recommend sealing all fastener heads.





at time of inspection

Garage roof beyond it's intended service life- OK exposed nails in garage ridge cap shingle- seal to prevent water intrusion

2. Walls

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| < | | | | |

Observations:

- No major system safety or function concerns noted at time of inspection.
- Personal items in garage block complete inspection of all floor, wall and ceiling areas.
- Personal items prevent complete inspection.
- Exterior walls could benifit from a new coat of paint

3. Anchor Bolts

Poor

Observations:

• The anchor bolte were inspected and appear to be serviceable.

4. Floor Condition

Poor

Materials: Bare concrete floors noted.

Common cracks noted.

5. Rafters & Ceiling

Poor

Observations:

Observations:

- Dimensional lumber wood ceiling joists.
- Visible areas appear satisfactory, at time of inspection.

| 6. Electrical |
|---|
| Observations: Social Fair Poor N/A None Observations: Some outlets not accessible due to furniture and or stored personal items. |
| 7. GFCI |
| Good Fair Poor N/A None |
| Observations: No GFCI protection present, suggest installing GFCI protected receptacles for safety. |
| 8. 240 Volt |
| Good Fair Poor N/A None |
| 9. Exterior Door |
| Good Fair Poor N/A None |
| 10. Fire Door |
| Good Fair Poor N/A None |
| 11. Garage Door Condition |
| Good Fair Poor N/A None Materials: One 7' Newer steel door |
| Observations: No deficiencies observed. |
| 12. Garage Door Parts |
| Observations: The garage door appeared functional during the inspection. |
| 13. Garage Opener Status |
| Good Fair Poor N/A None |
| 14. Garage Door's Reverse Status |
| Good Fair Poor N/A None |
| 15. Ventilation |
| Good Fair Poor N/A None |
| |
| 16. Vent Screens |
| Observations: Vent screens noted as functional. |
| 17. Cabinets |
| Good Fair Poor N/A None Observations: |
| No deficiencies observed. Appeared functional and in satisfactory condition, at time of inspection. |

18. Counters

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Observations:

- Plastic laminate tops noted.
 The counter tops are noted as having loose Formica at the backsplash. We recommend having a qualified contractor re-fasten it.

19. Wash Basin

| Good | Fair | Poor | N/A | None |
|------|------|------|----------|------|
| | | | | |
| | | | / | |

Exterior Areas

1. Doors

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| ~ | | | | |

2. Window Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| ~ | | | | |

3. Siding Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| < | | | | |

Materials: Full brick and Vinyl siding, wood frame construction, concrete / block foundation Observations:

• No major system safety or function concerns noted at time of inspection.

4. Eaves & Facia

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| / | | | | |
| | | | | |

Observations:

• Soffits at the home appeared to be in serviceable condition at the time of the inspection.

5. Exterior Paint

| ood | Fair | Poor | N/A | None |
|-----|------|------|----------|------|
| | | | | |
| | | | ✓ | |
| | | | | |

6. Stucco

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | |
| | | | _ | |

Roof

| 1 | R | 0 | റ | f | C | O | n | d | it | io | n | ۱ |
|---|---|---|---|---|---|---|---|---|----|----|---|---|
| | | | | | | | | | | | | |

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| < | | | | |

Observations:

• No major system safety or function concerns noted at time of inspection.

2. Flashing

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| < | | | | |

3. Chimney

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | > | | | |
| | | | | |

Observations:

- No major system safety or function concerns noted at time of inspection.
 Chimney Mortar shows sign of deterioration. Recommend having repaired as necessary.





minor tuck pointing needed on chimmney

weathered mortor joints - tuck pointing needed

4. Sky Lights

| Good | Fair | Poor | N/A | None |
|------|------|------|----------|------|
| | | | | |
| | | | / | |
| | | | • | |

5. Spark Arrestor

| Good | Fair | Poor | N/A | None |
|------------|------|------|-----|------|
| | | | | |
| <i> </i> | | | | |

6. Vent Caps

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | |

7. Gutter

| | Good | Fair | Poor | N/A | None |
|---|----------|------|------|-----|------|
| | | | | | |
| | / | | l | l | l |
| ı | - | | | | |

Observations:

- No major system safety or function concerns noted at time of inspection.
 Maintenance Tip: Keep gutters cleared of organic debris to prevent downspouts from being clogged causing overflow at gutters, ensure that all downspouts have extensions/splash blocks to carry water away from the foundation and ensure that sprinkler system does not spray siding or windows of house.

Attic 1. Access Good Fair Poor N/A Observations: · Bedroom Closet. 2. Structure Fair N/A None 3. Ventilation N/A Fair Poor None 4. Vent Screens Poor Fair N/A Good Observations: · Vent screens noted as functional. 5. Duct Work N/A Observations: Consult qualified roofing contractor to install roof vent Bath exhaust fan terminates in attic. This can lead to condensation in the attic and possibly promote microbial growth 6. Electrical N/A Fair Poor None Good 7. Attic Plumbing Observations: galvanized vent pipe 8. Insulation Condition Poor N/A Materials: Blown in cellulose insulation noted. Depth: Insulation averages about 8 inches in depth. recommend adding 6 to 8 more inches of insulation 9. Chimney Good Poor N/A None Observations: • Crown and Flashing intact where visible. Loose bricks observed. Brick and mortar deterioration observed; repair advised. Handy man or mason 10. Exhaust Vent Poor N/A Fair Good Observations: Kitchen exhaust fan Functional.

Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

| be consulted if you would like further testing. |
|---|
| 1. Bar |
| Good Fair Poor N/A None |
| |
| |
| 2. Cabinets |
| Good Fair Poor N/A None |
| |
| |
| O Calling Face |
| 3. Ceiling Fans |
| Good Fair Poor N/A None Observations: |
| Operated normally when tested, at time of inspection. |
| |
| 4. Closets |
| Good Fair Poor N/A None |
| |
| |
| 5. Door Bell |
| Good Fair Poor N/A None |
| Observations: |
| Operated normally when tested. |
| 6. Doors |
| Good Fair Poor N/A None |
| Observations: |
| • Hollow wood doors. |
| |
| 7. Electrical |
| Good Fair Poor N/A None Observations: |
| It is HIGHLY recommended to(have a qualified electrician) install an Arc |
| Fault Circuit Interrupter breaker in place of the the one currently protecting |
| the bedroom circuits, in the near future it will be a requirement and is a very |
| safe and sound update. |
| 9. Socurity Pare |
| 8. Security Bars Good Fair Poor N/A None |
| |
| |
| O Overla Delevia |
| 9. Smoke Detectors |
| Good Fair Poor N/A None Observations: |
| Operated when tested. |
| |

Bedrooms

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

| 1 | н | 00 | oti | i∧r | 10 |
|---|---|----|-----|-----|----|

Locations: North East#1 • South

2. Cabinets

| Good | Fair | Poor | N/A | None |
|------|------|------|----------|------|
| | | | | |
| | | | / | |
| 1 | | ı | 1 1 | |

3. Ceiling Fans

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| ~ | | | | |
| | | | | |

Observations:

• Operated normally when tested, at time of inspection.

4. Closets

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| > | | | | |

5. Doors

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| / | | | | |

6. Electrical

| е | Non | N/A | Poor | Fair | Good |
|---|-----|-----|------|------|------|
| | | | | | 7 |
| | | | | | |

Observations:

2-prong outlets -

The home contained outdated, ungrounded 2-prong electrical outlets. Although this condition may have been commonly considered safe or acceptable at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing condition to meet generally-accepted current standards.

7. Fireplace

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | ~ | |

8. Floor Condition

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| | | | | |
| / | | | | |
| | | | | |

Flooring Types: Carpet is noted.

9. Security Bars

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | / | |

10. Smoke Detectors

Observations:

• There were no smoke detectors present in the bedroom(s).

| | | | | _ | | |
|---|---|-----|------|----------|-----|-------|
| 1 | 1 | ١٨/ | all. | $C \cap$ | ndi | iti∩n |

| Good | Fair | Poor | N/A | None | Materials: Plaster walls noted. |
|------|------|------|-----|------|---------------------------------|
| | | | | | Materials. Plaster walls noted. |
| V | | | | | |

12. Window-Wall AC or Heat

| Good | Fair | Poor | N/A | None |
|------|------|------|----------|------|
| | | | | |
| | | | ' | |

13. Window Condition

| Good | Fair | Poor | N/A | None | Materials: Vinyl framed double hung window noted. |
|------|------|------|-----|------|--|
| | | | | | I materials. Virlyi framed double hung window noted. |
| | | | | | |

14. Ceiling Condition

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| | | | | |
| ' | | | | |

Materials: There are plaster ceilings noted.

15. Patio Doors

| Good | ган | FUUI | IN/A | None |
|------|-----|------|------|------|
| | | | | |
| | | | | |
| | | | | l |
| • | | | | |

Observations:

• The sliding patio door was functional during the inspection.

16. Screen Doors

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| | | | | |
| ' | | | l | l |
| | | l | | |

Observations:

• Sliding door screen is functional.

Bathroom

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring..

| problems within the walls of under the flooring |
|---|
| 1. Locations |
| Locations: Master Bathroom |
| 2. Cabinets |
| Observations: Appeared functional and in satisfactory condition, at time of inspection. |
| 3. Ceiling Condition |
| Good Fair Poor N/A None Materials: There are plaster ceilings noted. |
| 4. Counters |
| Observations: There is normal wear noted for the age of the counter tops. |
| 5. Doors |
| Observations: No major system safety or function concerns noted at time of inspection. |
| 6. Electrical |
| Good Fair Poor N/A None |
| 7. GFCI |
| Observations: No GFCI protection present, suggest installing GFCI protected receptacles for safety. Reversed polarity, hot and neutral reversed and other terms used for electric receptacles are usually easily corrected by minor wiring adjustments at the specified item. When these conditions are noted in this report, a |

8. Exhaust Fan

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| / | · | | | |

Observations:

to ensure safety.

• The fan terminates improperly in the attic. This can create excessive moisture. Recommend directing the vent towards the exterior to allow for proper ventilation.

licensed electrician should be consulted for repairs/replacement as needed

9. Floor Condition

| Good | Fair | Poor | N/A | None | |
|------|------|------|-----|------|--|
| / | | | | | |

Materials: Carpet is noted. • Sheet vinyl flooring is noted.

| 10. Heating |
|--|
| Good Fait Poor N/A None Observations: |
| • Central heating noted in this room. At the time of the inspection, all |
| appeared to be functioning and in serviceable condition. |
| 11. Mirrors |
| Good Fair Poor N/A None |
| |
| 12. Plumbing |
| Good Fair Poor N/A None |
| |
| 13. Security Bars |
| Good Fair Poor N/A None |
| |
| 14. Showers |
| Good Fair Poor N/A None Observations: |
| • functional |
| 15. Shower Walls |
| Good Fair Poor N/A None Observations: |
| |
| Ceramic tile noted. |
| Ceramic tile noted. Evidence of repair observed. |
| • Evidence of repair observed. 16. Bath Tubs |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None Observations: |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None Observations: • Tub has been refinished, suggest taking care when cleaning to protect the |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None Observations: • Tub has been refinished, suggest taking care when cleaning to protect the surface. |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None Observations: • Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None • Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure Good Fair Poor N/A None Observations: |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None • Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure Good Fair Poor N/A None Observations: • Curtain present at the shower enclosure. |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None • Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure Good Fair Poor N/A None Observations: |
| Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None Observations: Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure Good Fair Poor N/A None Observations: Curtain present at the shower enclosure. 18. Sinks |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None Observations: • Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure Good Fair Poor N/A None Observations: • Curtain present at the shower enclosure. 18. Sinks Good Fair Poor N/A None Observations: • Curtain present at the shower enclosure. |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None Observations: • Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure Good Fair Poor N/A None Observations: • Curtain present at the shower enclosure. 18. Sinks Good Fair Poor N/A None V |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None Observations: • Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure Good Fair Poor N/A None Observations: • Curtain present at the shower enclosure. 18. Sinks Good Fair Poor N/A None V N/A None Observations: • Curtain present at the shower enclosure. |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None Observations: • Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure Good Fair Poor N/A None Observations: • Curtain present at the shower enclosure. 18. Sinks Good Fair Poor N/A None V |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None • Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure Good Fair Poor N/A None • Curtain present at the shower enclosure. 18. Sinks Good Fair Poor N/A None • Curtain present at the shower enclosure. 19. Toilets Good Fair Poor N/A None • Observations: • Operated when tested. No deficiencies noted. • toilet old. Recommend replacement by a qualified Plumber |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None • Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure Good Fair Poor N/A None Good Fair Poor N/A None • Curtain present at the shower enclosure. 18. Sinks Good Fair Poor N/A None • Curtain present at the shower enclosure. 19. Toilets Good Fair Poor N/A None • Observations: • Operated when tested. No deficiencies noted. • toilet old. Recommend replacement by a qualified Plumber 20. Window Condition |
| • Evidence of repair observed. 16. Bath Tubs Good Fair Poor N/A None • Tub has been refinished, suggest taking care when cleaning to protect the surface. 17. Enclosure Good Fair Poor N/A None • Curtain present at the shower enclosure. 18. Sinks Good Fair Poor N/A None • Curtain present at the shower enclosure. 19. Toilets Good Fair Poor N/A None • Observations: • Observations: • Operated when tested. No deficiencies noted. • toilet old. Recommend replacement by a qualified Plumber 20. Window Condition |

Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

| 1 | Ca | hi | in | ط | ŀc |
|---|------|----|----|--------------|----|
| | I () | | ш | \leftarrow | к |

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | |
| | | | | |

2. Counters

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | / | | | |

Observations:

- Plastic laminate tops noted.
- Laminated countertop is swollen and beginning to blister @ rear of sink basin. Recommend further evaluation by qualified counter top manufacturer. This is caused by water intrusion beneath the laminate

3. Dishwasher



Observations:

- Operated.
- No loop in drain line. Run drain line as high as possible under sink then down to drain pipe to prevent drain water back flow into the fresh water supply. this is called a "high loop"

4. Doors

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | 1 | |

5. Garbage Disposal

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | |
| | | | | |

Observations:

• Operated - appeared functional at time of inspection.

6. Microwave



Observations:

- Inoperable at the time of inspection.
- Recommend review by a qualified appliance technician for repair or replacement as necessary.

7. Cook top condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Observations:

• IRREGULAR INSTALLATION: Range projects too far out and impedes on the full and proper opening of dishwasher door. Eventually this condition will damage the front of the oven door. Recommend qualified individual reset range further into counter by approximately one inch.

8. Oven & Range

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | |
| | | | | |

Observations:

- All heating elements operated when tested.
- IRREGULAR INSTALLATION: Range projects too far out and impedes on the full and proper opening of dishwasher door. Eventually this condition will damage the front of the oven door. Recommend qualified individual reset range further into counter by approximately one inch.

| 9. Sinks |
|--|
| Good Fair Poor N/A None Observations: |
| • Faucet leaks at base. may be the cause of delamination at countertop |
| backsplash. Consult licensed plumber for repair |
| Sacropiaerii. Cericult licerioca piarriser for repair |
| 10. Drinking Fountain |
| Good Fair Poor N/A None |
| |
| |
| 11. Spray Wand |
| Good Fair Poor N/A None |
| |
| |
| 12. Hot Water Dispenser |
| Good Fair Poor N/A None |
| |
| |
| 13. Soap Dispenser |
| Good Fair Poor N/A None |
| |
| |
| 44 Teach Occupation |
| 14. Trash Compactor |
| Good Fair Poor N/A None |
| |
| |
| 15. Vent Condition |
| Good Fair Poor N/A None Materials: Exterior Vented |
| |
| |
| 16. Window Condition |
| Good Fair Poor N/A None Materials: Vinyl framed double hung window noted. |
| Observations: |
| • Peeling paint observed @ lower portion of window opening and window sill |
| suggest scraping and painting as necessary. |
| |
| 17. Floor Condition |
| Materials: Sheet vinyl flooring is noted. |
| |
| |
| 18. Plumbing |
| Good Fair Poor N/A None Observations: |
| • Flex drain observed, these are subject to frequent clogging. suggest further |
| evaluation by a licensed plumber |
| |
| 19. Ceiling Condition |
| Materials: There are plaster ceilings noted. |
| |
| |
| |

| 20. Security Bars |
|--|
| Observations: No security bars are present in this room. |
| 21. Patio Doors |
| Good Fair Poor N/A None |
| 22. Screen Doors |
| Good Fair Poor N/A None |
| 23. Electrical |
| Good Fair Poor N/A None |
| 24. GFCI |
| Observations: No GFCI protection present, suggest installing GFCI protected receptacles for safety. |

| | Good | ı alı | F 001 | IN/A | NULLE | ı Materials: Plaster walls noted. |
|-----|------|-------|-------|------|-------|-----------------------------------|
| - 1 | | | | l | l . | i Materiais. Plaster walls noted. |
| - 1 | | | | l | l | |
| - 1 | | | | l | l . | |
| | • | | | l | l | |
| L | | | | | | ı |

| Laundry |
|--|
| 1. Locations Locations: Downstairs |
| 2. Cabinets Good Fair Poor N/A None Observations: No deficiencies observed. |
| 3. Counters Good Fair Poor N/A None |
| 4. Dryer Vent Good Fair Poor N/A None Observations: • plastic flex pipe used for dryer exhaust. This can become a fire hazard over time. Recommend replacing with metal venting piping - handyman or DYI |
| 5. Electrical Good Fair Poor N/A None |
| 6. GFCI Good Fair Poor N/A None Observations: ◆ GFCI in place and operational |
| 7. Exhaust Fan Good Fair Poor N/A None V |
| 8. Gas Valves Good Fair Poor N/A None Observations: • Gas shut off valves were present and functional. |
| |
| 9. Wash Basin Good Fair Poor N/A None Observations: Slow drain at sink. Recommend clearing. Faucet drips. |
| Observations: Slow drain at sink. Recommend clearing. |
| Observations: Slow drain at sink. Recommend clearing. Faucet drips. 10. Floor Condition Good Fair Poor N/A None Materials: Vinyl squares (tiles) are noted |

| 1 | 3 | Ceil | lina | Con | dition |
|---|---|-------|------|-----|--------|
| | • | ~ ~ . | | | |

| Good | Fair | Poor | N/A | None | Materials |
|----------|------|------|-----|------|-----------|
| | | | | | Materials |
| <i>V</i> | | | | | |

Materials: Open beam ceiling construction noted.

14. Security Bars

| Good | Fair | Poor | N/A | None |
|------|------|------|----------|------|
| | | | | |
| | | | V | |

Observations:

• No security bars are present in this room.

15. Doors

| Fair | Poor | N/A | None |
|------|------|-----------|---------------|
| | | | |
| | | | |
| | | | |
| | Fair | Fair Poor | Fair Poor N/A |

16. Window Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| / | | | | |

Materials: Glass blocks noted in window openings.

Observations:

• Peeling paint, efflorescence observed, suggest scraping and painting as necessary. - handyman or DYI

Heat/AC

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

1. Heater Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| < | | | | |

Materials: The furnace is located in the basement Materials: Gas fired forced hot air.

Observations:

- Fuel Furnace: Last service date is over one year ago, or is unable to be determined. Although this unit appears to be operating properly from controls, there are areas which cannot be seen without specialized equipment and training. One such area is the combustion chamber / heat exchanger where cold air blows across the "fire box", becoming the hot air that circulates throughout your home. During the life span of any furnace. this metal wall may develop a crack or a broken weld, allowing carbon monoxide to circulate throughout the home. This is why furnace specialists recommend a complete inspection annually; consider having unit inspected by certified HVAC technician.
- Furnace has reached it's intended service life

2. Heater Base

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| | | | | |
| / | | | | |

Observations:

The heater base appears to be functional.

3. Enclosure

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| / | | | | |

4. Venting



Observations:

- Metal single wall chimney vent pipe noted.
- Chimney liner and cap installed.

5. Gas Valves

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| | | | | |
| / | | | | |

Observations:

Gas shut off valves were present and functional.

6. Refrigerant Lines

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| | | | | |
| / | | | | |

Observations:

No defects found.

7. AC Compress Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| < | | | | |

Compressor Type: Electric

Location: The compressor is located near the patio area. • The compressor is located on the exterior south.

Observations:

- Appeared functional at the time of inspection.
- Annual HVAC service contract is recommended.

8. Air Supply

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| < | | | | |

Observations:

- The return air supply system appears to be functional.
- We recommend sealing all holes and gaps for maximum effectiveness.

9. Registers

| | Good | Fair | Poor | N/A | None |
|---|----------|------|------|-----|------|
| ı | | | | | |
| ı | / | | l | l | |
| ı | | | | | |

Observations:

• The return air supply system appears to be functional.

10. Filters

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| < | | | | |

Location: Located inside heater cabinet.

Observations:

• MAINTENANCE: The air filter(s) should be inspected at least monthly and cleaned or replaced as required. There are two types of filters commonly used: (1) Washable filters, (constructed of aluminum mesh, foam, or reinforced fibers) these may be cleaned by soaking in mild detergent and rising with water. Or (2) Fiberglass disposable filters that must be REPLACED before they become clogged. Remember that dirty filters are the most common cause of inadequate heating or cooling performance.

11. Thermostats

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Observations:

- Analog, non-programmable type. Hallway
- IMPROVE: Non-programmable thermostats have no energy saving capabilities as do digital setback-type thermostats. Recommend an upgrade to a modern, digital programmable thermostat. This could yield a saving of up to \$180 per year in energy costs.

| Water Heater |
|--|
| 1. Base |
| Observations: The water heater base is functional. |
| 2. Heater Enclosure |
| Observations: The water heater enclosure is functional. |
| 3. Combusion |
| Observations: The combustion chamber appears to in functional condition. |
| 4. Venting |
| Good Fair Poor N/A None |
| 5. Water Heater Condition |
| Heater Type: Gas Observations: • Tank appears to be in satisfactory condition no concerns. • Water heater is past the end of its typical service life but functioning satisfactorily. Recommend budgeting for replacement. |
| 6. TPRV |
| Good Fair Poor N/A None |
| 7. Number Of Gallons |
| Good Fair Poor N/A None |
| 8. Gas Valve |
| Good Fair Poor N/A None |
| 9. Plumbing |
| Materials: Galvanized Observations: No deficiencies observed at the visible portions of the supply piping. |
| 10. Overflow Condition |
| Materials: Copper Observations: • Appears to be in satisfactory condition no concerns. |
| 11. Strapping |
| Observations: • The water heater is not strapped. |

Electrical

1. Electrical Panel



Location: Panel box located in basement. • South side of the house.

Location: No Sub Panels located.

Observations:

• No major system safety or function concerns noted at time of inspection at main panel box.

2. Main Amp Breaker

| Good | Fair | Poor | N/A | None | |
|------|------|------|-----|------|--|
| ~ | | | | | |

Observations:

100 amp

3. Breakers in off position

| Good | Fair | Poor | N/A | None | |
|----------|------|------|-----|------|-----|
| | | | | | ١ (|
| / | | | | | ŀ |

Observations:

• 0

4. Cable Feeds

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| < | | | | |
| • | | | | |

Observations:

• There is an overhead service drop noted.

5. Breakers

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| / | | | | |
| " | | | | |

Materials: Copper non-metallic sheathed cable noted.

Observations:

• All of the circuit breakers appeared serviceable.

6. Fuses

| Good | Fair | Poor | 11/7 | None |
|------|------|------|------|------|
| | | | | |
| | | | •/ | |
| | | | | |

| Foundation |
|--|
| 1. Slab Foundation |
| Good Fair Poor N/A None |
| |
| 2. Foundation Perimeter |
| Observations: • Evidence of past water penetration observed. possibly a minor flood. Area was observed to be dry and was likely painted some time ago |
| 3. Foundation Walls |
| Observations: • minor Efflorescence observed; this is a mineral deposit left behind from exterior water infiltration.at south window • Mildew observed, which is an indication of inadequate ventilation. • Block foundation/ walls |
| 4. Cripple Walls |
| Good Fair Poor N/A None |
| 5. Ventilation |
| Good Fair Poor N/A None |
| 6. Vent Screens |
| Good Fair Poor N/A None |
| 7. Access Panel |
| Good Fair Poor N/A None |
| 8. Post and Girders |
| Observations: Support Material: Steel Beam Material: Steel |
| 9. Sub Flooring |
| Observations: Plywood sheathing sub floor. Limited review only in small utility room due to 95% finished ceiling in lower level. |
| 10. Anchor Bolts |
| Observations: The anchor bolts were not visible. |

11. Foundation Electrical

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| ~ | | | | |

12. Foundation Plumbing

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| > | | | | |

Observations:

- 3/4 inch copper
 Water meter is located in a poor location that prevents clear working space for review and repair of plumbing system.
 Copper line is not protected from concrete, Ideally a plastic sleeve is
- recommended around pipe before pouring of slab to prevent damage if settlement of concrete should occur.<FYI>

13. Sump Pump

| Good | Fair | Poor | N/A | None |
|------|------|------|----------|------|
| | | | | |
| | | | ' | |

14. Ducting

| Good | Fair | Poor | N/A | None |
|---------------------------------------|------|------|-----|------|
| | | | | |
| \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | | |

Basement/Crawlspace

| <u> </u> |
|--|
| 1. Walls |
| Materials: **BASEMENT** • Fully finished basement. Observations: • No deficiencies were observed at the visible portions of the structural components of the home. • Evidence of past water penetration observed. Check with owner about history |
| 2. Insulation |
| Good Fair Poor N/A None |
| 3. Windows |
| Good Fair Poor N/A None Materials: Glass blocks noted in window openings. |
| 4. Plumbing Materials |
| Materials: Appears Functional. • Appears Functional. Observations: Galvanized and Copper |
| 5. Basement Electric |
| Good Fair Poor N/A None |
| |
| 6. GFCI |
| Observations: Outlets in the basement were not Ground Fault Circuit Interrupter (GFCI) protected. Adding GFCI protection is relatively inexpensive. All electrical work should be performed by a qualified electrical contractor. Consider adding GFCI protection of these outlets. |
| 7. Access |
| Observations: handrail loose. Tighten with household screwdriver- DYI |
| 8. Stairs |
| Good Fair Poor N/A None Observations: Low head room noted at stairway location. |
| 9. Railings |
| Observations: - Hand/Guardrail is loose. Recommend review for repair as necessary for safety. |
| 10. Slab Floor |
| Good Fair Poor N/A None |
| |

| 1 | 1 | Fii | าiร | hed | d F | loor |
|---|---|-----|-----|-----|-----|------|

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| ~ | | | | |

12. Drainage

| Good | Fair | Poor | N/A | None |
|--|------|------|-----|------|
| | | | | |
| ✓ | | | | i i |
| <i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i> | | | | 1 1 |
| | | | | |

13. Sump Pump

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | |
| | | | • | |

14. Framing

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| / | | | | |

Observations:

- Appears Functional.
- Some areas are not visible for inspection due to wall/ceilings covered which prevents review of structural members.

15. Subfloor

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| / | | | | l |
| • | | | | |

Observations:

· Limited inspection due to finished ceiling.

16. Columns

| Good | Fair | Poor | N/A | None |
|----------|------|------|-----|------|
| | | | | |
| / | | | | |

Observations:

• No deficiencies were observed at the visible portions of the structural components of the home.

17. Piers

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | 1 | |

18. Basement/Crawlspace Ductwork

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| V | | | | |

Photos



some portions of the garage were not viewable due to item storage




exterior walls of the garage could benifit from a new coat of paint



cracking in garage floor typical for it's age



Grounds



chimmney cap ok . monitor annually



Roof Vent Caps



proper size aluminum service entrance cable

| Resid | lentia | l Eart | hqual | ke Hazards Report | | |
|----------------------------|--------|--------|---------------|---|--|--|
| Yes | No | N/A | Don't Know | | | |
| | | | | 1. Is the water heater braced, strapped, or anchored to resist falling during an earthquake? | | |
| Yes | No | N/A | Don't Know | 2 Is the house anchored or holted to the foundation? | | |
| | | | | 2. Is the house anchored or bolted to the foundation? | | |
| Yes | No | N/A | Don't Know | If the house has cripple walls: a. Are the exterior cripple walls braced? | | |
| | | | | | | |
| Yes | No | N/A | Don't Know | b. If the exterior foundation consists of unconnected concrete piers and | | |
| | | | | posts, have they been strengthened? | | |
| Yes | No | N/A | Don't Know | 4. If the exterior foundation, or part of it, is made of unreinforced masonry, has | | |
| | | | | it been strengthened? | | |
| Yes | No | N/A | Don't Know | 5. If the house is built on a hillside: a. Are the exterior tall foundation walls braced? | | |
| Yes | No | N/A | Don't | | | |
| | | | Know | b. Were the tall posts or columns either built to resist earthquakes or have they been strengthened? | | |
| Yes | No | N/A | Don't | they been strengthened? | | |
| | | | Know | 6. If the exterior walls of the house, or part of them, are made of unreinforced masonry, have they been strengthened? | | |
| Yes | No | N/A | Don't | masonly, have they been strongthened: | | |
| | | | Know | 7. If the house has a living area over the garage, was the wall around the garage dooropening either built to resist earthquakes or has it been | | |
| | | | | strengthened? | | |
| Yes | No | 1 | Don't Know | 19. In the house outside on Alguint Priole Forthquake Foult Zone (zones | | |
| | | | | 8. Is the house outside an Alquist-Priolo Earthquake Fault Zone (zones immediately surrounding known earthquake faults)? | | |
| Yes | No | 1 | Don't Know | 10. In the house outside a Sciemic Hazord Zano (zono identified as auccentible | | |
| | | | | 9. Is the house outside a Seismic Hazard Zone (zone identified as susceptible to liquefication or landsliding)? | | |
| | | | | | | |
| EXEC | UTE | D BY | : | | | |
| (Selle | r) | | | (Seller) Date | | |
| l ackno to one weakn | or mo | re que | stions, | his form, completed and signed by the seller. I understand that if the seller has answered "No" or if seller has indicated a lack of knowledge, there may be one or more earthquake . | | |
| (Buye | er) | | | (Buyer) Date | | |

Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expenses to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all of the pages of the report as the summary alone does not explain all the issues. All repairs must be done by a licensed &bonded trade or profession. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

| Grounds | <u> </u> | receipts, warranties and permits for the work done. |
|------------------|---------------------------|--|
| Page 6 Item: 8 | GFCI | Conduit seperation at both front porch and rear patio electric feeds. Exposed wires. Recommend further evaluation by a licensed electrician. |
| Attic | | |
| Page 14 Item: 5 | Duct Work | Bath exhaust fan terminates in attic. This can lead to condensation in the attic and possibly promote microbial growth |
| Bathroom | | |
| Page 19 Item: 7 | GFCI | Reversed polarity, hot and neutral reversed and other terms used for electric receptacles are usually easily corrected by minor wiring adjustments at the specified item. When these conditions are noted in this report, a licensed electrician should be consulted for repairs/replacement as needed to ensure safety. |
| Page 19 Item: 8 | Exhaust Fan | The fan terminates improperly in the attic. This can create excessive moisture. Recommend directing the vent towards the exterior to allow for proper ventilation. |
| Kitchen | | |
| Page 21 Item: 3 | Dishwasher | No loop in drain line. Run drain line as high as possible under sink then down to drain pipe to prevent drain water back flow into the fresh water supply. this is called a "high loop" |
| Page 22 Item: 9 | Sinks | Faucet leaks at base. may be the cause of delamination at countertop backsplash. Consult licensed plumber for repair |
| Page 22 Item: 18 | Plumbing | Flex drain observed, these are subject to frequent clogging. suggest further evaluation by a licensed plumber |
| Page 23 Item: 24 | GFCI | No GFCI protection present, suggest installing GFCI protected receptacles for safety. |
| Laundry | | |
| Page 24 Item: 4 | Dryer Vent | plastic flex pipe used for dryer exhaust. This can become a fire hazard over time. Recommend replacing with metal venting piping - handyman or DYI |
| Page 24 Item: 9 | Wash Basin | Slow drain at sink. Recommend clearing.Faucet drips. |
| Water Heater | | |
| Page 28 Item: 5 | Water Heater Condition | Water heater is past the end of its typical service life but functioning satisfactorily. Recommend budgeting for replacement. |